

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 01/01/91 through 01/31/91

Customer number: None Veh#: 316 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
1/4/91		14,455	GB	R	F	HVAC		No Heat From Heater, Ordered Thermostat. (18529)
1/7/91		15,876	GB	H	F	EMIS		Vehicle Taken To Ford For Emission Test. (19950)
1/28/91		16,327	GB	R	F	MAIN		Changed Engine Oil And Filter-Level Was 1/2Qt. Low. Drained 3130g, Added 3500g.(20401)
1/29/91		16,502	GB	R	F	HVAC		No Heat From Heater, Replaced Therostat & Gasket(20576)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 01/01/91 through 01/31/91

Customer number: None Veh#: 317 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
1/7/91		15,881	GB	H	F	EMIS		Vehicle Taken To Ford For Emission Test. (19950)
1/23/91		18,066	GB	R	F	MAIN		Changed Engine Oil & Filter-Level Was 1/2qt. Low. Drained 3004g. Added 3201g. (22135)
1/24/91		18,603	GB	R	F	ELSY		Replaced Left Headlight Bulb, Part # 9004. (22672)
1/29/91		20,238	GB	R	F	ELSY		Horn Inop. Needs Horn, Part Ordered. (24307)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 01/01/91 through 01/31/91

Customer number: None Veh#: 318 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
1/14/91		3,936	GB	R	F	MISC		Vehicle Back On Schedule After Being Repaired At Al Bennett Ford. (8006)
1/16/91		4,826	GB	R	F	ENOA		Added 1qt of Engine Oil, 798g. (8896)
1/17/91		5,256	GB	H	F	BAEN		Returned Vehicle To Ford Dealer To Check On Oil Consumption. (9326)
1/18/91		5,266	GB	R	F	BAEN		Vehicle Back On Schedule After Repair For Oil Consumption. (9336)
1/23/91		5,524	GB	H	F	BAEN		Engine Still Has High Oil Consumption, Vehicle Returned To Ron Hurley. (9594)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 12/01/90 through 12/31/90

Customer number: None Veh#: 315 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
12/3/90		1,116	GB	H	F	MAIN	1	Changed engine oil and filter (PF56) Oil level was full. Drained 3120g, installed 3200g of oil. (5,237)
12/19/90		8,115	GB	H	F	MAIN	1	Changed engine oil - level was 1/2 qt. low. Drained 2400g, added 2810g. (12,236)
12/20/90		8,551	GB	R	F	ENOA	1	Added 1 qt. of engine oil, 810g. (12,672)
12/27/90		10,682	GB	R	F	WISY	1	Right wiper arm stripped at transmission. Removed wiper arm and ordered parts. (14,803)
12/27/90		11,427	GB	R	F	ELSY	2	Low beam out on both headlights. Replaced both headlight bulbs. (part #9004). (15,548)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 12/01/90 through 12/31/90

Customer number: None Veh#: 316 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
12/11/90		4,456	GB	R	F	WISY	1	Windshield molding loose on left side. Silicone in windshield molding. (8,530)
12/13/90		6,072	GB	R	F	ENOA	1	Added 1 qt. of engine oil, 798g. (10,146)
12/18/90		8,167	GB	R	F	MAIN	1	Changed engine oil - level was 1/4 qt. low. Drained 2642g, added 2791g. (12,241)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 12/01/90 through 12/31/90

Customer number: None Veh#: 317 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
12/1/90		1,406	GB	R	F	ENOA	1	Added 1 qt. of engine oil, 806g. (5,475)
12/5/90		2,723	GB	R	F	ELSY	1	Left headlight inop. Replaced left headlamp bulb. (6,792)
12/6/90		3,452	GB	R	F	MAIN	1	Changed engine oil and filter - level was full. Drained 3186g, added 3210g. (7,521)
12/19/90		10,227	GB	R	F	ENOA	1	Added 1 qt. of engine oil, 800g. (14,296)
12/20/90		10,654	GB	R	F	MAIN	1	Changed engine oil - level was 1/2 qt. low. Drained 2360g, added 2806g. (14,723)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 12/01/90 through 12/31/90

Customer number: None Veh#: 318 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
12/10/90		3,208	GB	R	F	MAIN	1	Changed engine oil and filter - level was 1 pt. low. Drained 2884g, added 3208g. (7,278)
12/11/90		3,912	GB	H	F	MISC	1	Vehicle involved in accident. Driver lost control on gravel road and hit a tree. Vehicle taken to Ford dealer for repair. (7982)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 11/01/90 through 11/30/90

Customer number: None Veh#: 317 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
11/17/90		0	GB	R	F	MISC	1	Start of Test (4,069)

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 11/01/90 through 11/30/90

Customer number: None Veh#: 318 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
11/17/90		0	GB	R	F	MISC	1	Start of Test (4,070)
11/18/90		174	GB	R	F	ENOA	1	Added 1 qt. engine oil. <u>847 grams (4.244)</u>

SYCRON CORPORATION - SPECIFIC OCCURRENCE REPORT

Report from: 11/01/90 through 11/30/90

Customer number: None Veh#: 316 Engine: 1.9L SEFI

Date	Shift	Test miles to date	Loc.	Status	Client Occ.	Type Occ.	Occ. Order	Comments
11/16/90		0	GB	R	F	MISC	1	Start of Test (4,074)
11/16/90		76	GB	R	F	WISY	1	Driver noticed stone chip on lower right corner of windshield. OK to continue on schedule. (4,150)
11/30/90		1,172	GB	R	F	MAIN	1	Changed oil and filter (PF51). Removed 3010 g installed 3218 g of oil. Took sample of new oil. (5,246)